

NON-PUBLIC?: N  
ACCESSION #: 9005030270  
LICENSEE EVENT REPORT (LER)

FACILITY NAME: Beaver Valley Power Station, Unit 1 PAGE: 1 OF 03

DOCKET NUMBER: 05000334

TITLE: Reactor Trio on "C" Steam Generator Low Level and Steam  
Flow/Feedwater Flow Mismatch Due to Closure of "C" Main Feedwater  
Regulating Valve

EVENT DATE: 03/30/90 LER #: 90-007-00 REPORT DATE: 04/ /90

OTHER FACILITIES INVOLVED: N/A DOCKET NO: 05000

OPERATING MODE: 1 POWER LEVEL: 100

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR  
SECTION:  
50.73(a)(2)(iv)

LICENSEE CONTACT FOR THIS LER:

NAME: Thomas P. Noonan, General Manager TELEPHONE: (412) 643-1258  
Nuclear Operations

COMPONENT FAILURE DESCRIPTION:

CAUSE: X SYSTEM: SJ COMPONENT: TD MANUFACTURER: F130  
REPORTABLE NPRDS: N

SUPPLEMENTAL REPORT EXPECTED: No

ABSTRACT:

On 3/30/90 at 1541 hours, with the Unit in Power Operation at 100% reactor power, alarms indicating a Loop "C" steam flow/feedwater flow mismatch, followed by a "C" steam generator (SG) level deviation were received. The operators noted closure of the "C" Main Feedwater Regulating Valve, FCV-FW-498. The operator tried to manually open FCV-FW-498, however, the valve would not respond. At 1544 hours, a reactor trip on "SG "C" Low Level & Feedwater Flow Low" occurred. Control Room personnel entered Emergency Operating Procedures, E-0 and ES-0.1, to stabilize the plant in Hot Standby. The cause for the reactor trip was the closure of FCV-FW-498, in response to insufficient instrument air pressure supplying the valve positioner. Air pressure had degraded due to moisture in the filter in the instrument air regulator for the valve positioner. High moisture was present due to the

instrument air dryer being unavailable. The moisture in the instrument air system has been removed and the instrument air dryer has been returned to service. There were no safety implications as a result of this event. The plant systems responded as designed (all rods inserted, turbine trip occurring and auxiliary feedwater initiating on low SG level), with the exception of FCV-FW-498, to place the plant in Hot Standby. This event is bounded by Updated Final Safety Analysis Report, Section 14.1.8.

END OF ABSTRACT

TEXT PAGE 2 OF 03

#### DESCRIPTION

On 3/30/90 at 1541 hours, with the Unit in Power Operation (Operating Mode 1) at 100% reactor power, Control Room personnel received an annunciator indicating a Loop "C" steam flow/feedwater flow mismatch, followed by a "C" steam generator (SG) level deviation. The operators observed the "C" Loop feedwater flow and noted that the "C" SG feedwater flow and the level were rapidly decreasing. The operator also noted closure of the "C" Main Feedwater Regulating Valve, FCV-FW-498, even though the valve positioner controller was outputting a 100% full open signal. Using the manual controller, the operator tried to manually open FCV-FW-498, however, the valve would not respond. At 1544 hours, a reactor trip on "SG "C" Low Level & Feedwater Flow Low" occurred. Control Room personnel entered Emergency operating Procedure, E-0 "Reactor Trip and Safety Injection" and transitioned to ES-0.1 "Reactor Trip Response", after verifying that a Safety injection Signal was not required, to stabilize the plant in Hot Standby (Operating Mode 3).

#### CAUSE OF THE EVENT

The cause for the reactor trip was the partial closure of the "C" Main Feedwater Regulating Valve, FCV-FW-498. The closure of FCV-FW-498 resulted from an insufficient supply of instrument air to the valve positioner. Moisture in the instrument air supply had plugged the filter in the air regulator for the current-to-pneumatic valve positioner for FCV-FW-498, causing the valve to close. This moisture was present in the instrument air system as a result of the instrument air dryer being out of service. While the air dryer was out of service, the air compressors' discharge was directed through the instrument air bypass filters. These filters are two-stage filters consisting of a wool felt pad and an absorbent silica gel canister. Although the filters are not as efficient as the dryer at removing moisture, they are capable of providing dry air on a temporary basis. On 3/21/90, the air dryer was removed from service

for maintenance. The instrument air bypass filters remained in service for an extended period of time. During this period, although the station initiated the vendor recommended compensatory actions of blowing down the filter once per eight hours, moisture accumulated in the air lines, resulting in this event.

TEXT PAGE 3 OF 03

### CORRECTIVE ACTION

The following corrective actions have been taken as a result of this event:

1. Operations personnel, utilizing the Emergency Operating Procedures, stabilized the plant in Hot Standby.
2. Air operated valves in the Turbine Building and Primary Auxiliary Building were blown down to remove any moisture within the instrument air lines. Small amounts of moisture was found in various valves within both buildings.
3. The Main Feedwater Regulating Valves were inspected and repaired as necessary. The instrument air lines for these valves were blown down to remove any moisture.
4. The instrument air dryer was returned to service.
5. A temporary diesel air compressor was placed in service to supplement the existing station air compressors and to allow the use of an additional air dryer, which could not be used because the station air compressors did not have sufficient capacity to supply the new air dryer and maintain instrument air pressure.
6. An engineering evaluation of the instrument air system is being performed.
7. The anti-rotation pin in the plug assembly for the "C" Main Feedwater Regulating Valve was repaired.

### SAFETY IMPLICATIONS

There were no safety implications as a result of this event. The plant systems responded as designed (all shutdown bank and control rods inserted, turbine trip occurring and auxiliary feedwater initiating on low SG level following the SG level "shrink" resulting from the loss of secondary load), with the exception of the "C" Main Feedwater Regulating

Valve which did not fully close and was isolated by closing the motor operated feedwater isolation valve, to place the plant in Hot Standby (Operating Mode 3) conditions. This event, feedwater perturbations due to valve malfunctions, is bounded by the Updated Final Safety Analysis Report (UFSAR), Section 14.1.8, "Loss of Normal Feedwater".

#### REPORTABILITY

This event was reported to the Nuclear Regulatory Commission at 1810 hours on 3/30/90, in accordance with the requirements of 10 CFR 50.72.a.2.ii. This written report is being submitted in accordance with the requirements of 10 CFR 50.73.a.2.iv.

ATTACHMENT 1 TO 9005030270 PAGE 1 OF 2

Duquesne Light Telephone (412) 393-6000  
Nuclear Group  
P.O. Box 4  
Shipping port, PA 15077-0004

April 30, 1990  
ND3MNO:2058

Beaver Valley Power Station, Unit No. 1  
Docket No. 50-334, License No. DPR-64  
LER 90-007-00

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

Gentlemen:

In accordance with Appendix A, Beaver Valley Technical Specifications, the following Licensee Event Report is submitted:

LER 90-007-00, 10 CFR 50.73.a.2.iv, "Reactor Trip on "C" Steam Generator Low Level and Steam Flow/Feedwater Flow Mismatch Due to Closure of "C" Main Feedwater Regulating Valve".

Very truly yours,

T. P. Noonan  
General Manager  
Nuclear Operations

JT/sl

Attachment

ATTACHMENT 1 TO 9005030270 PAGE 2 OF 2

April 30, 1990  
ND3MNO:2058  
Page two

cc: Mr. William T. Russell  
Regional Administrator  
United States Nuclear Regulatory Commission  
Region 1  
475 Allendale Road  
King of Prussia, PA 19406

C.A. Roteck, Ohio Edison  
76 S. Main Street  
Akron, OH 44308

Mr. Peter Tam, BVPS Licensing Project Manager  
United States Nuclear Regulatory Commission  
Washington, DC 20555  
J. Beall, Nuclear Regulatory Commission,  
BVPS Senior Resident Inspector

Dave Amerine  
Centerior Energy  
6200 Oak Tree Blvd.  
Independence, Ohio 44101

INPO Records Center  
Suite 1500  
1100 Circle 75 Parkway  
Atlanta, GA 30339

G.E. Muckle,  
Factory Mutual Engineering, Pittsburgh  
3 Parkway Center  
Room 217  
Pittsburgh, PA 15220

Mr. J.N. Steinmetz, Operating Plant Projects Manager  
Mid Atlantic Area  
Westinghouse Electric Corporation

Energy Systems Service Division  
Box 355  
Pittsburgh, PA 15230

American Nuclear Insurers  
c/o Dottie Sherman, ANI Library  
The Exchange Suite 245  
270 Farmington Avenue  
Farmington, CT 06032

Mr. Richard Janati  
Department of Environmental Resources  
P.O. Box 2063  
16th Floor, Fulton Building  
Harrisburg, PA 17120

Director, Safety Evaluation & Control  
Virginia Electric & Power Co.  
P.O. Box 26666  
One James River Plaza

\*\*\* END OF DOCUMENT \*\*\*

---